\$16,460											
Pebble Hills Elementary	<b>(</b> 59/ )	96	\$ @ & K.	2							
IC1	27	36			1	1	2	2			
Port IC-1	3	12				1	00	2			
Site Total Quantity			1	2	1	2	2	4	11	0	
Site Total Hardware Cost			\$41,487	\$16,748	\$2,575	\$3,860	\$322	\$1,288	\$16,847	\$0	
\$83,127											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost				<u></u>							
\$16,460											- 2 a a a a 5 a a a a a a a
Pasodale Elementary	35	48	\$2.75 <b>1</b> 5550	1355	<u> </u>		\$255 <u>5</u> 3555	25.79.22.22	<u>, , , , , , , , , , , , , , , , , , , </u>		<u> </u>
1C1	22	24			11		0	2			
IC2	10	12				1	_ 0	2			
Port IC-1	3	12				11	0	2			
Site Total Quantity			1	1	11	2	0	6	11	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$3,860	\$0	\$1,932	\$16,847	\$0	
\$75,075									<u> </u>		
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280			<b> </b>							<del></del>	
Site Installation Cost	<u> </u>								ļ		
\$16,460	<u> </u>	<u> </u>									
Presa Elementary	33	48	100	1655					1		
IC1	12	36			11	11	2	2		<u> </u>	
Port IC-1	9	12				1	0	2		ļ	<u> </u>
Site Total Quantity			11	1	1	2	2	4	1	0	
Site Total Hardware Cost	<u> </u>		\$41,487	\$8,374	\$2,575	\$3,860	\$322	\$1,288	\$16,847	\$0	<del></del>
<u>\$74,753</u>			ļ <u>.</u>	ļ					<u> </u>		<u> </u>
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280		ļ			ļ			<u> </u>		<u> </u>	
Site Installation Cost		ļ	<u> </u>			· · · · · · · · · · · · · · · · · · ·					···
\$16,460		1.2 M. S. W. S. W. S. M. S. W. S. W.		and the second s							
Ramona Elementary	20	48	155553 <b>1</b> 55555	<u> </u>					1.22.1		
IC1	10	12	<u> </u>			1	0	2			
IC2	10	12				11	0	2		<u> </u>	

Site Total Quantity			1	1	0	2	0	4	1	0	ļ
Site Total Hardware Cost			\$41,487	\$8,374	\$0	\$3,860	\$0	\$1,288	\$16,847	\$0	
\$71,856											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$16,460											
Robert F Kennedy PreK	>>>20	48	37.4	100					228 A 22		
IC1	35	36			1	11	2	2			
IC2	20	24			1		0	2			
Site Total Quantity	<del></del>		1	1	2	1	2	4	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$5,150	\$1,930	\$322	\$1,288	\$16,847	\$0	
\$75,398						<u></u>	ļ			<b></b>	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280				ļ				<u> </u>			
Site Installation Cost							<u> </u>				
\$16,460											
Sageland Elementary	~~24	48	<u> </u>	< 14 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5					1.		
IC1	10	12				1	0	2	ļ		
JC2	11	12				11	0	2			
Port IC-1	4	12				11	0	2		ļ	
Site Total Quantity			11	1	0	3	0	6	1	0	
Site Total Hardware Cost			<b>\$41,48</b> 7	\$8,374	\$0	\$5,790	\$0	\$1,932	\$16,847	\$0	
\$74,430				<u> </u>							
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0_	\$2,280	\$0	
\$2,280											
Site Installation Cost								Ļ			
\$16,460		Total Control of Free Control	The form to the Work West William	a on a trans or sold a fact a sold a sol							
Scotsdale Elementary	<b>∕</b> ∖∶∖51⊹⊹∴	96	3/3/ <u>/</u> 1/3/3/	2	<u> </u>	<u> </u>			1/	<b>1</b>	<u> </u>
IC1	30	36			11	1	22	2	ļ		
Port IC-1	5	12				1	0	2			<del> </del>
Site Total Quantity			11	2	11	2	2	4	1	0	
Site Total Hardware Cost			\$41,487	\$16,748	\$2,575	\$3,860	\$322	\$1,288	\$16,847	\$0	
\$83,127								<u> </u>			
Site Total Maintenance Cost			\$0	\$0_	\$0	\$0	\$0	\$0	\$2,280	\$0	L

the state of the s

	t			Ι	т	<del></del>					
\$2,280						<del> </del>					
Site Installation Cost					ļ	<b></b>		<u> </u>		<del></del>	<del> </del>
\$16,460			and the World Water Street William Street			- ಎಂಬು ಎಂಬು ಉಪ ಬಾತ್ರಗ್ನು					
South Loop Elementary	28	-48	<u>*                                    </u>	<u> </u>		M. (2009)	15 X 15 5 7 7 8 8 3 5 1 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		<u> </u>		
IC1	16	24			1	ļ	0	2			
Port IC-1	66	12				1	0	2			
Site Total Quantity			11	11	1	11	0	44	11	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$1,930	\$0	\$1,288	\$16,847	\$0	Ĺ
\$72,501			<u></u>			<u></u>					
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280			 								
Site Installation Cost	<b>.</b>										
\$16,460										Professional and the	
Thomas Manor Elementary	27	48	XXX <b>1</b> .5553	S 19 S S	<u> </u>		\$5,55 <b>5</b> 555		1		
IC1	20	24	<u> </u>		1	ļ	0	2			
IC2	14	24	<u> </u>		1		0	2			
Site Total Quantity	<u></u>		11	1	2	0	0	4	11	0	
Site Total Hardware Cost			\$41, <u>4</u> 87	\$8,374	\$5,150	\$0	\$0	\$1,288	\$16,847	\$0	
\$73,146					<u> </u>		<u> </u>	<u> </u>			
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280	<u> </u>				ļ						
Site Installation Cost						· 				<del> </del>	
\$16,460		<u> </u>	<u></u>	<u> </u>			and the second s	And with the state of the state			
Tierra del Sol Elementary	39	48	2012	2/1/202	<u> </u>	<u> </u>			12.21		
IC1	22	24			11		0	2			
Port IC-1	5	12				11	0	2			
Site Total Quantity			11	1	1	1	0	4	11	0	
Site Total Hardware Cost	<u> </u> 		\$41,487	\$8,374	\$2,575	\$1,930	\$0	\$1,288	\$16 <u>,</u> 847	\$0	<u></u>
\$72,501								ļ <u> </u>			
Site Total Maintenance Cos			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$16,460	<u> </u>										
Vista Hills Elementary	57 .57	96	4.04 (100 s	2 💎	<u> </u>	16-8-8KS	<u> </u>	MARKARY	\(\frac{1}{2}\)		
Port IC-1	11	12	<u> </u>		]	11	0	2		L	<u> </u>

Port IC-2	8	12				1	0	2			
Site Total Quantity			1	2	0	2	0	4	1	0	
Site Total Hardware Cost			\$41,487	\$16,748	\$0	\$3,860	\$0	\$1,288	\$16,847	\$0	
\$80,230										<u> </u>	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost					-						
\$16,460								Co. N. Dec. W. J. L. W. Dec. W. Dec. W. Co.	Octobration State Control	Andrew Constitution of Property	Program to the control of the control of
Ysleta Elementary	<. 23	48	<u> </u>	<u> </u>					1		
IC1	11	12				11	0	2		<b>-</b>	
IC2	6	12				1	0	2		ļ	,
IC3	10	12				1.	0	22			
IC4	10	12				11	0	2			
IC5	10	12	<u> </u>			1	0	2			
Site Total Quantity			11	11	0	5	0	10	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$0	<b>\$9,650</b>	\$0	\$3,220	\$16,847	\$0	
\$79,578											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280							ļ. <u></u>				
Site Installation Cost			<u> </u>								
\$16,460									to the the second of the second of the	10-40-40-40-40-50-60-5	and the second
Ysleta Pre-K	30/	48<sup 2 48</td <td>20047000</td> <td>(1/2/2)</td> <td>2.62.62.63</td> <td>\$100 XXXXX</td> <td><u> </u></td> <td>2 11/1/11/20</td> <td>78.41 ( <u>) (</u></td> <td>1.00</td> <td>00000000</td>	20047000	(1/2/2)	2.62.62.63	\$100 XXXXX	<u> </u>	2 11/1/11/20	78.41 ( <u>) (</u>	1.00	00000000
Port IC-1	7	12				1	0	2			
Site Total Quantity		12	11	1	0	1	0	2	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$0	\$1,930	\$0	\$644	\$16,847	\$0	
\$69,282	<u> </u>		<u> </u>		-						
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$16,460											
Camino Real Middle	32	48	4						4		
IC1	10	12				1	0	2			
IC2	31	36	<del> </del>		1	1	2	2			
102	1 31	30	<del></del>	<u> </u>	<u> </u>	l'				L	L

Port IC-1	2	12				1	0	2			
Site Total Quantity			1	1	1	3	2	6	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$5,790	\$322	\$1,932	\$16,847	\$0	
\$77,327										<u> </u>	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	_\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$21,230											N 10 10 10 10 10 10 10 10 10 10 10 10 10
Desert View Middle	ै- े <b>47</b> ः	48		3 ( <b>1</b> 558)	<u> </u>	<u> </u>		(**** <u>*</u> *****	(: (: ji/::://	<u> </u>	<u> </u>
IC1	14	24			11		0	2	<u> </u>		
IC2	23	24			11		0	2		ļ	
Port IC-1	1	12				1	0	2			
Site Total Quantity			11	1	2	1	0	6	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$5,150	\$1,930	\$0	\$1,932	\$16,847	\$0	
\$75,720	<del>-</del>		<del></del>					<u> </u>	<del>-</del>		
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280				<u> </u>		ļ. <del></del>		ļ	<u> </u>	<b></b>	
Site Installation Cost											
\$21,230	Alt William word wide More No.										
Eastwood Middle	30	48	1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1	<u>///1////</u>	<u> </u>				<u> </u>		
IC1	32	36			1	1	2	2	ļ		
Port IC-1	7	12				1	0	2			
Site Total Quantity			1	1	1	2	2	4	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$3,860	\$322	\$1,288	\$16,847	\$0	
\$74,753		ļ	 						<del> </del>		
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280								<u> </u>			
Site Installation Cost		<b></b>									
\$21,230		V successive de la comp	. The Park State of Earlie	rat Villa e MeliMethia		CANAL PROPERTY.	101000000000000000000000000000000000000	Prince Comment			
Eastwood Knolls K-8	29	48	\$ \$ \$ <b>1</b> \$ \$ \$ \$ \$	\$\\$\ <b>1\<u>\$\\$\\$</u></b>		<u> </u>		1	(\$'\\$' <b>t</b> \\$\\$\\$		
IC1	20	24	ļ		1		0	2			
IC2	21	24	<u> </u>		1	<u> </u>	0	2			ļ
Port IC-1	3	12	ļ	<u> </u>	<del> </del>	1	0	2	1	<del> </del>	}
Site Total Quantity		ļ	11	11	2	1	0	6	1	0	
Site Total Hardware Cost	L	1	\$41,487	\$8,374	\$5,150	\$1,930	\$0	\$1,932	\$16,847	\$0	

\$75,720											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280										ļ	
Site Installation Cost											
\$21,230											
Hillcrest Middle	29	48	9	1/2/2		\$100 \$100 B			4.2		
IC1	10	12				1	0	2		ļ	<u> </u>
IC2	35	36			1	1	2	2		ļ	
Site Total Quantity			11	1	1	2	2	4	11	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$3,860	\$322	\$1,288	\$16,847	\$0	
\$74,753									<u> </u>	<u> </u>	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280							<del></del>			<u> </u>	
Site Installation Cost						·		, 			<u> </u>
\$21,230				and the second of the second	The sales are also the sales at the Market	an man alim i la mal alim i alim i alim i	n in the second sec		THE WEST ACTORISTS OF THE		WANGAN TARAK
Indian Ridge Middle	30	48	<u> </u>	3 1 3					1		
1C1	27	36			1	1	2	2		<u> </u>	
IC2	10	12				11	0	. 2		<u> </u>	
Port IC-1	1	12				11	0	2		<del></del>	
Site Total Quantity			11	11	1	3	22	6	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$5,790	\$322	\$1,932	\$16,847	\$0	
\$77,327			 					ļ			
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$21,230		<u> </u>									
Parkland Middle	<b>54</b>	96	<u> </u>	<b>′</b> ′′′′′′′′′′′′′′′′′′′′′′′′′′′′′′′′′′′	<u> </u>		<u> </u>		2001		
IC1	20	24			1		0	2	<u> </u>		
Port IC-1	11	12				1	0	2			
Port IC-2	1	12				11	0	2			
Site Total Quantity			1	2	1	2	0	6	1	0	
Site Total Hardware Cost			\$41,4 <u>87</u>	\$16,748	\$2,575	\$3,860	\$0	\$1,932	\$16,847	\$0	<del></del> -
\$83,449						<u>.                                    </u>					
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											

Site Installation Cost											
\$21,230	end ander 1818 albah di aktor i	en Barber Barber Bar	രച്ചിക്ക് ക്ക്ക്ക്ക് ആ	Marai e II. Sukuraya (1907)	CA CANAL KANAKA	(et/post, et/stock, et/stock), et			Radion No. 35		l Personalas anakan
Parkview Middle	20	48							<u> </u>	_	
Site Total Quantity			11	11	0	0	0	0	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$0	\$0	\$0	\$0	\$16,847	\$0	
\$66,708									<u>.</u>		
Site Total Maintenance Cost			<b>\$</b> 0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280										<b></b>	ļ
Site Installation Cost											
\$21,230											
Ranchland Hills Middle	37	48	3.4						1/2/2		
IC1	20	24			1		0	2			ļ
Port IC-1	11	12				1	0	2		ļ	<del> </del>
Site Total Quantity			11	1	1	1	0	4	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$1,930	\$0	\$1,288	\$16,847	\$0	
\$72,501	·									<u> </u>	<u> </u>
Site Total Maintenance Cost			\$0	\$0	<u>\$</u> 0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280										<u> </u>	<u> </u>
Site Installation Cost										<b> </b>	
\$21,230									28282828282		
Rio Brayo Middle	>> 23	48	<u> </u>	1000					1		
IC1	21	24			1	<u> </u>	0	2		<del> </del>	
IC2	8	12		ļ		1	0	2		<b> </b>	<u> </u>
1C3	1	12				1	0	2			
IC4	10	12				1	0	2		<u> </u>	
Site Total Quantity			_11	11	1	3	0	8	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$5,790	\$0	\$2,576	\$16,847	\$0	
\$77,649				<u> </u>	<u></u>		<u> </u>				
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280				<u> </u>							
Site Installation Cost								ļ		<u> </u>	
\$21,230						ļ	<u> </u>				
Riverside Middle	56	96		2	1999	<u> </u>			<u> </u>		
IC1	11	12				11	0	2			
Port IC-1	9	12				11	00	2			

Site Total Quantity			1	2	0	2	0	4	1	0	<del>-</del> -
Site Total Hardware Cost			\$41,487	\$16,748	\$0_	\$3,860_	\$0	\$1,288	\$16,847	\$0	·
\$80,230											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost							ļ				
\$21,230			<u> </u>								A STATE A STAT
Valley View Middle	32	48	2221223					1	2222122		<u> </u>
IC1	10	12	<u> </u>			11	0	2	<del> </del>		
IC2	34	36			1	1	2	2	ļ		
Site Total Quantity			1	1	1	2	2	4	11	0	<u> </u>
Site Total Hardware Cost	<u></u>		\$41,487	\$8,374	\$2,575	\$3,860	\$322	\$1,288	\$16,847	\$0	<del></del>
\$74,753			<u> </u>				ļ		<u> </u>	<u> </u>	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost			<u> </u>				<u> </u>	<u> </u>	<u> </u>		
\$21,230			<u> </u>								AND IN A VIEW WERE NOTED IN
Ysleta Middle	<b>62</b>	96		2	(3:3838.68	<u> </u>	15.55	<u> </u>	(		<u> </u>
IC1	18	24			1		0	2	ļ		
Port IC-1	11	12				11	0	2	<u> </u>	<del></del>	
Site Total Quantity			1	2	11	11	0	4	11	0	
Site Total Hardware Cost			\$41,487	\$16,748	\$2,575	\$1,930	\$0	\$1,288	\$16,847	\$0	
\$80,875			<u> </u>								
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280					<u> </u>						
Site Installation Cost											
\$21,230			<u> </u>				<u> </u>			<u> </u>	
									<u> </u>		` 
		<u> </u>									
Bel Air High	>>50	96	\$\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	2.5	<u> </u>	\$55555555		5558558	<u> </u>		
IC1	63	72			3		3	2			
IC2	33	36	<u> </u>		1	1	2	2	<u> </u>		
IC3	43	48			2		2	2			
1C4	17	24	<u> </u>		1		0	2			
IC5	37	_48	L		2		2	2			

Port IC-1	5	12				1	0	2			
Site Total Quantity			_ 1	2	9	2	9	12	1	0	
Site Total Hardware Cost			\$41,487	\$16,74 <u>8</u>	\$23,175	\$3,860	\$1,449	\$3,864	\$16,847	\$0	
\$107,430											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$26,155											
Del Valle High	66	96		2							X86866
IC1	72	84		i	3	1	4	2		<u> </u>	
IC2	21	24			11		0	2			
IC3	10	12				1	0	2			
IC4	38	48			2		0	2			
IC5	20	24			1		0	2			
Port IC-1	11	12				1	0	2			
Port IC-2	1	12				1	0	2			<u> </u>
Site Total Quantity			11	2	7	4	10	14	1	0	
Site Total Hardware Cost			\$41,487	\$16,748	\$18,025	\$7,720	<b>\$1,6</b> 10	\$4,508	\$16,847	\$0	
\$106,945											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	<u> </u>
\$2,280			<b>1</b>					· · · · · · · · · · · · · · · · · · ·			
Site Installation Cost											
\$26,155											
EastWood High	25	48	2222A3222	200 M 2008	10000000	100000000000000000000000000000000000000			22.4		
IC1	32	36			1	1	2	2			<u> </u>
IC2	32	36			1	1	2	2			
IC3	71	84			3	1	4	2			
Port IC-1	8	12				1	0	2			
Site Total Quantity			1	1	5	4	8	8	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$12,875	\$7,720	\$1,288	\$2,576	\$16,847	\$0	
\$91,167											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost						} 		 	 		
\$26,155											

	121	144	\$1.500 E	q					1	W 98 8 8 8 8 8 8	1
Hanks High	<u> </u>	72			3		3	2		<u>ja mija ja ja kultua kuju nija</u>	
IC1	30	36			1	1	2	2			
IC3	8	12				1	0	2			
·	11	12				1	0	2			
Port IC-1 Port IC-2		12				1	0	2			
		12	1	3	4	4	5	10	1	0	
Site Total Quantity			\$41,487	\$25,122	\$10,300	\$7,720	\$805	\$3,220	\$16,847	\$0	
Site Total Hardware Cost			<del>\$41,467</del>	φ20,122	\$10,500	Ψέτευ	Ψοσο	Ψ0,220	φ10,047		
\$105,501			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
Site Total Maintenance Cost			\$0	<b>⊅</b> 0	\$0	φ0	<b>\$</b> 0	Φ0	\$2,200	_ \$0	
\$2,280				<u> </u>							
Site Installation Cost										<u> </u>	
\$26,155	2000 CONT. Z	96		2					1		18 (8 (8 (8 (8 (8 (8 (8 (8 (8 (8 (8 (8 (8
Parkland High	52	1		2 / · · · · ·	1		0	2			
IC1	1 <u>6</u>	24					0	2			
IC2	5	12				1	0	4	1	0	
Site Total Quantity			1	2	1 00.575	<del> </del>	\$0	\$1,288	\$16,847	\$0	
Site Total Hardware Cost			\$41,487	\$16,748	\$2,575	\$1,930	20	\$1,200	\$10,047	<b>\$</b> 0	
\$80,875					***	Φ0	ro.	60	#0.000	\$0	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280				<del> </del>							
Site Installation Cost											
\$19,075	NEW TRANSPORTER		A. A. A. A. A. A. A. A.							V6.4%. ~% ~% ~% ~%	
Riverside High		96	************	2					.1		
IC1	34	36			1	1	2	2			
IC2	10	12		<del></del>	1	11	0	2			
IC3	29	36		<u> </u>		11	2	2		_	
IC4	29	36			1	1	2	2			<u> </u>
IC5	35	36			11	1	2	2		•	
Port IC-1	11	12	· ——	<u> </u>		11	0	2			
Site Total Quantity		ļ	1	2	4	6	8	12	1	0	
Site Total Hardware Cost			\$41,487	\$16,748	\$10,300	\$11,580	\$1,288	\$3,864	\$16,847	\$0	
\$102,114		<u> </u>		ļ							
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280										<u></u>	

and the second of the second o

Site Installation Cost											
\$26,155											
Ysleta High	44	48	S. 2013 22	\$3.500			S. S. J. S.		200		
IC1	42	48			2		2	2			
IC2	28	36			1	1	2	2			
IC3	8	12				1	0	2		<u> </u>	
IC4	20	24			1		0	2			
1C5	15	24			1		0	2			
Site Total Quantity			1	1	5	2	4	10	11	0	
Site Total Hardware Cost	<del></del>		\$41,487	\$8,374	\$12,875	\$3,860	\$644	\$3,220	\$16,847	\$0	
\$87,307											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost											
\$26,155								The second secon		a ar na faltar air ar ar ar ar 18 Sa	year dala baran Tarant bankar
Tejas School	39	- 48	\$\$\$ <b>\$\$</b> \$\$\$\$\$\$	<u> </u>	7333333		<u> </u>		<u> </u>		<u> </u>
Site Total Quantity			1	1	0	0	0	0	11	0	ļ. — ···
Site Total Hardware Cost			\$41,487	\$8,374	\$0	\$0	\$0	\$0	\$16,847	_\$0	
\$66,708									ļ <u>-</u>	ļ <u> </u>	
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											
Site Installation Cost								<u> </u>	ļ		
\$19,075									<u> </u>		at the market cause. In market
AST	20	48	???? <b>1</b> ????	27.71272	77579777777	7277777	57575 5576	77777777	2/2/12/2/2		
IC1	40	48			2		2	2			
1C2	40	48			2		2	2		ļ	<u> </u>
Port IC-1	1	12			1 1 1000	1	0	2			
Site Total Quantity			1	1	4	1	4	6	1	0	ļ
Site Total Hardware Cost		<u> </u>	\$41,487	\$8,374	\$10,300	\$1,930	\$644	\$1,932	\$16,847	\$0	
\$81,514								ļ			
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280					<u> </u>	<u> </u>	ļ <u>.</u>		19128		<u> </u>
Site Installation Cost		<u> </u>	<b></b>								
\$26,155							5.07.00 47.00 57.00 57.00 57.00		and the second second second		Sea and an an an an an an an
Cesar Chavez Academy 🔀	1.5	48							<u> </u>		

IC1	5	12				1	0	2		0	
Port IC-1	11	12				1 _	0	2			
Port IC-2	7	12				1	0	2			
Site Total Quantity			1	1	0	3	0	6	1	0	<u></u>
Site Total Hardware Cost			\$41,487	\$8,374	\$0	\$5,790	\$0	\$1,932	\$16,847	\$0	
\$74,430											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280											<del></del>
Site Installation Cost								<u>.</u>	ļ		
\$19,075											
Student Entrepreneur Center	<b>`</b> `\ 20	48		4/3/3/	// 2/2/2/2				1000		
IC1	5	12				1	0	2	ļ	ļ	
Site Total Quantity			1	1	0	1	0	2	1	0	
Site Total Hardware Cost	<u></u>		\$41,487	\$8,374	\$0	\$1,930	\$0	\$644	\$16,847	\$0	
\$69,282									<u> </u>		
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	<del></del>
\$2,280						<u> </u>	ļ. — — — — — — — — — — — — — — — — — — —				
Site Installation Cost		<u> </u>					ļ		ļ	<del> </del> -	
\$19,075	and other transfers			The Late of the State of West Work	V 5.005, 1435, V 5.05, A.143	<b>173</b> 2434345454574545					5 7 18 72 1 72 1 72 1 72 1 7 1 7 1 7 1 7 1 7 1
Ysleta Comm Learning Cent		48	<u> </u>	1/4/4					1		
1C1	20	24			1		0	2	<del></del>	0	
Site Total Quantity		<del> </del>	1	1	1	0	0	2	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$2,575	\$0	\$0	\$644	\$16,847	\$0	<del></del>
\$69,92 <u>7</u>			<del></del>				<del> </del>		<del>                                     </del>		
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	<del></del>
\$2,280					Light specific to				<u> </u>	<del> </del>	
Site Installation Cost					ļ		<del> </del>			<del> </del>	
\$19,07 <u>5</u>	38.43.43.43.44.44.44.44.44.44.44.44.44.44.										
Plato Academy	<b>///30</b> ///	48	li e		777787777	N 43 4301 5302 4 11 40,43 6			T		
Site Total Quantity			1	1	0	0	0	0	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$0	\$0	\$0	\$0	\$16,847	\$0	<del></del>
\$66,708		<del>                                     </del>							<del> </del>	-	<del></del>
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	\$2,280	\$0	
\$2,280		ļ					<u> </u>			<u> </u>	
Site Installation Cost			<b> </b>	L		<u> </u>	1		1	<u> </u>	<u></u>

\$19,075				ra a la cluberta en			nandranananan di Pakaban		1974 Y 2010 2 2 4 2 4 2 4 2 4 2 4 2 4 2 4 2 4 2 4	Regionalists versionis	D\$\$#\$\#\$\#\#\#\#\#\
ACAC (Central Office)	<b>∕</b> ∜∴ 27	48		<u> </u>	2		3			1	2
IC1	64	72			3		3	2		ļ	
IC2	83	84			3	1	4	_2			<u> </u>
Site Total Quantity			0	0	_8	1	10	4		11	22
Site Total Hardware Cost			\$0	\$0	\$20,600	\$1,930	\$1,610	\$1,288		\$3,541	\$174,136
\$203,105											
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	_\$0		\$0	\$22,202
\$22,202									ļ	<u> </u>	
Site Installation Cost											
\$76,925			<u></u>					1 d 1 m 2 d a m 1 d d d			
Service Center	30	48	\$\$\$\$\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			\$ 5555555			1		
IC1	20	24			1		0	2			
IC2	15	24			1		0	2	<u></u>		
Site Total Quantity		<u></u>	11	1	2	0	0	4	1	0	
Site Total Hardware Cost			\$41,487	\$8,374	\$5,150	\$0	\$0	\$1,288	\$16,847	\$0	<u>.</u>
\$73,146					1						
Site Total Maintenance Cost			\$0	\$0	\$0	\$0	\$0	\$0	<b>\$2,280</b>	\$0	- <u> </u>
\$2,280											
Site Installation Cost											
\$19,075											
Total Ports	4976	7284									
								<u> </u>			
Total Hardware Cost											
\$4,950,454											
Total Maintenance Cost											
\$161,282					والجدد ز						
Installation Cost										L	
\$1,229,165											
IBM & Cisco Engineer & Tec	nnical										
Up to 440 hours @ \$235/ ho											
\$103,400											
Training											
\$38,900 _											
	<del>                                     </del>	<del> </del>	<del>                                     </del>						1		

the state of the s

										<u> </u>
		Base 6509 Configuration	6509 48-port 10/ 100 Telco Module		12-port 10/100 Tx plus 2-GBIC ports Enterprise	GigaStack GBIC and cable	1000BaseSx GBIC	3660 Router	8-PORT 1000Base GBIC Switch Enterprise Software	7513 Routers
1	 	61	74	97	116	84	334	61	1	2

## Main Closet Chassis Option - 8-1000BaseSx ports, 10/100 ports and Sx GBIC on site details

WS-C6509	Catalyst 6509 Chassis	1	\$6,441	\$6,441
WS-CAC-1300W	Catalyst 6000 1300W AC Power Supply	1	\$2,574	\$2,574
WS-CAC-1300W/2	Catalyst 6000 1300W Second 1300W AC Power Supply	1	\$2,574	\$2,574
CAB-7513AC	AC Power Cord North	2	\$0	\$0
SFC6K-SUP-5.3.2	Catalyst 6000 Supervisor Flash Image, Release 5.3 (2) Catalyst 6000 Supervisor	1	\$0	\$0
WS-X6K-SUP1A-MSFC	Engine1-A, 2GE, Plus MSFC & PFC Catalyst 6000 Supervisor	1	\$19,330	\$19,330
MEM-C6K-FLC16M	PCMCIA Flash Mem Card 16MB Option	1	\$258	\$258
MEM-MSFC-64MB	Catalyst 6000 MSFC Mem, 64MB DRAM	1	\$0	\$0
SC6MMSFCB-12.0.3XE	Cisco IOS Catalyst 6000 Family MSFC - Desktop	1	\$3,867	\$3,867
WS-X6408-GBIC	Catalyst 6000 8-port Gigabit Ethernet Module (Req. GBICs)	1	\$6,442	\$6,442
WS-X6248-TEL	Catalyst 6000 48-port 10/100 Telco Module	0	\$8,374	\$0
WS-G5484	1000Base-SX Short Wavelength GIBC Total Cost of Base	0	\$344	\$0
	Configuration			\$41,487

#### Cent I Office Routers - Two Cisco 7513s ( pport for 80-T1s AND 2-DS3s)

CISCO7513/4x2	Cisco 7513 13-Slot, 2 CyBus, 2 RSP4, Dual Power Supply	2	\$28,936.00	\$57,872.00
PWR-7513/4x2	Cisco 7513 /4x2 Dual AC Power Supply Option	2	\$0.00	\$0.00
CAB-7513AC	AC Power Cord North	4	\$0.00	\$0.00
S75BS-12.0.5XE	Cisco RSPX Series IOS Desktop/IBM	2	\$3,867.00	\$7,734.00
FR-WPP75	Cisco IOS RSPx Series WAN Packet Protocols/Netflow	2	\$3,222.00	\$6,444.00
RSP4	License Cisco 7500 Series Route Switch Processor 4	2	\$0.00	\$0.00
MEM-RSP4-128M	RSP4 128MB DRAM Option	2	\$1,160.00	\$2,320.00
MEM-RSP4-FLC16M	RSP4 Flash Card: 16MB Option Default	2	\$0.00	\$0.00
RSP4	Cisco 7500 Series Route Switch Processor 4	2	\$0.00	\$0.00
MEM-RSP4-128M	RSP4 128MB DRAM Option	2	\$1,160.00	\$2,320.00

MEM-RSP4-FLC16M	RSP4 Flash Card: 16MB Option Default	2	\$0.00	\$0.00
FEIP2-DSW-2TX	2-Port Fast Ethernet IP with Dist. Switching (100TX)	2	\$3,867.00	\$7,734.00
VIP2-40	Versatile Interface Processor-2, model 40	4	\$7,089.00	\$28,356.00
MEM-VIP240-64M	64 MB DRAM Option for VIP2- 40	4	\$387.00	\$1,548.00
PA-MC-8T1	8 Port Multichannel T1 Port adapter with Integrated CSU/	8	\$7,476.00	\$59,808.00
CT3IP-50	DSU Channelized DS3 Model 50 Interface Processor	0	\$27,067.00	\$0.00
MEM-VIP250-8M-S	8 Mbytes SRAM Option for VIP2-50/xIP-50	0	\$516.00	\$0.00
MEM-VIP250-128M-D	128 Mbytes DRAM Option for VIP2-50/xIP-50	0	\$1,160.00	\$0.00
				\$174,136.00

\$87,068.00

### Remote Campus Router - One Cisco 3660 per Campus (61 total) (Support for 2-T1s)

CISCO3662-AC	Dual 10/100 E Cisco 3660 6-slot Modular Router-AC with IP SW	61	\$7,540.00	\$459,940.00
CAB-AC	Power Cord, 110V	61	\$0.00	\$0.00
S366BP-12.0.5XK	Cisco 3660 Series IOS IP/IPX/AT/DEC PLUS	61	\$709.00	\$43,249.00
FL36-CU=	Cisco IOS 3600 Series IP to H323 (Downloadable Image Only)	61	\$2,385.00	\$145,485.00
MEM3600-16FC	16Mb Flash card for the Cisco 3600	61	\$773.00	\$47,153.00
MEM3660-32U96D	32-to-96MB DRAM Factory Upgrade for the Cisco 3660	61	\$2,475.00	\$150,975.00
NM-2CT1-CSU	2-port Channelized T1/ISDN-PRI with CSU Network Module	61	\$2,965.00	\$180,865.00
			\$16,847.00	

HOME CANCEL SAVE & EXIT HELP

FCC Form 471 Services Ordered and Certification Form



Applicant's Form Identifier:

Router/Campus Network Elec

Contact Person: Bill Richardson

Entity Number: 142115

Phone Number: (915) 434-1065

#### **IMPORTANT**

Please record this application's information in a secure place for future reference

471 Application Number: 179273
Entity Number of Billed Entity (Applicant): 142115
Security Code Number: 69507

Angle of the state of the state

Copyright 1997-1999 Schools and Libraries Division

**EXHIBIT** 

FCC Form 471 Services Ordered and Certification Form



Approval by OMB 3060-0806

Estimated Average Burden Hours Per Response: 4 hours

This form asks schools and libraries to list the eligible telecommunications-related services they have ordered and estimate the annual charges for them so that the Fund Administrator can set aside sufficient support to reimburse providers for services.

Please read instructions before beginning this application.

Applicant's Form Identifier: (Insert your own code to identify THIS Form 471)

Router/Campus

Form 471 Application #:

(inserted by Administrator)

l, Name of Billed Entity YSLETA INDEP SCHOOL DIST	RICT		2. Funding Year: 07/01/2000-06/30/2001
3. Entity Number 142115			
Street 9600 SIMS DR			
Ny EL PASO:	i programa Spiralis sk Spiralis sk	State TX	Zip Code 5Digit Zip Code 4Digit 79925 7200
b. Telephone number ext			c. Fax number
(_915) 434 - 0000			(_915 )_435
	o and a way		9521
E-mail Address brichardson@ysleta.i	sđ.t	enet	.edu
5. Type Of Applicant (Select only	11 W Z-7:79	#22 5 SCHOOLS	
Individual School (individual public of	NON-PRESENT	G)r. PH EXHIPP	) ) local district representing multiple schools)
O Library (including library system, libr		ijagyjalast (dasji	
Consortium (intermediate service age	ncies, stat	tes, state n	etworks, special consortia)
lf you selected "Consortium" in #5 above, cho entities.	ck here	_l if any	members are ineligible non-govermental
des Content Persons (Numera) & Republicanos paras a content de la conten	e ja	Сору	4a-d above to 6b-e below
Correct and/or add any Contact Person's info contact	ormation .	below as r	iecessary, then select your preferred mode of
6b. Street Address, P.O.Box, or Route N	lumber		
O 9600 SIMS DR	<u> 41 H H</u>		

O 6c. Telephone Number (10 digits + ext.)	( 915) 434 - 1065 ext
O 6d. Fax Vumber (10 digits)	( <u>915)</u> 435 - 9521
• 6e. 5-mail Address 50 :haracters max.)	brichardson@ysletalisd.tenet.edu

Service Service Committee of the service of the ser	nist D. Fesit Fo	Trong (Silvers)	g <b>w</b>
Copyright 1997-1999 Schools and Libraries Division			

1/14/00 7:12 PM

HOME CANCEL SAVE & EXIT HELP

# FCC Form 471 Services Ordered and Certification Form



Applicant's Form Identifier:

Router/Campus Network Elec

Contact Person: Bill Richardson

Entity Number: 142115

Phone Number: (915) 434-1065

7: THIS ITEM CANNOT BE FILED ONLINE. You may use this item ONLY to inform the fund administrator of Minor Contract Modifications for previously filed. Forms 471, and you may do so ONLY through manual filing on paper Please call 888-203-8100 for specific instructions.

8. Please provide your best estimate of the number of of the services ordered in THIS Form 471. Schools/school	chool districts complete 8a.
a. Number of students to be served 48000 b.	Number of library patrons to be
9. The following questions seek summary outcome in ordered in this Form 471 application. Please complete to THIS application.	formation based on the service conly those rows that are relevant
IFTHIS APPLICATION INCLUDES	Before After Order Order
a. Telephone service (for schools/school districts/consortia only). How many classrooms had phone service before and after your order?	
b. High-bandwidth voice/data/video service: How many buildings served before and after your order?	
c. High-bandwidth voice/data/video service: Highest speed to a building before and after your order?	
d. Dial-up Internet connections: How many before and after your order?	
e. Dial-up Internet connections: Highest speed before and after your order?	
f. Direct connections to the Internet: How many before and after your order?	
g. Direct connections to the Internet: Highest speed before and after your order?	
h. Internet access(for schools): How many rooms have Internet access before and after your order?	
i. Internet access(for libraries): How many buildings have Internet access before and after your order?	

mb back	100mb	bac
		X41 1111/1-16-14(A(1-11)
Salle is Co.		*12:13
	A TENNE TO SERVICE AND A	
. E Taning man prope	111 11 111	
	Palater	

HOME CANCEL SAVE & EXIT HELP





Applicant's Form Identifier: Router/Campus Network Elec

Entity Number: 142115

Contact Person: Bill Richardson

Phone Number: (915) 434-1065

**Bottom** 

<u>เต็ร์กากแกะระเด็กและเลง และเลง</u>	nilizar, a (51.016) a pracinga a	ા જિલ્લામાં કરવાનો ત્રુપે કાર્યો કર્ય
3. Urban or Rural: Urban	4. Total # of Students: 567	5, # of Students Eligible for NSLP: 511
6. %Students Eligible for NSLP (#5/ #4): 90:123%	7. Discount % from Discount : Matrix: 90%	8. Weighted Product (#4 X #7): 510:3
(etymeoraciookannakekaaraeyna)	Jackschoold and Angels and	្ត្រាស់ ខ្លាំង ខ្លាំ
3. Urban or Rural: Urban	4. Total # of Students: 554	5. # of Students Eligible for NSLP: 503
6. %Stridents Eligible for NSLP (#5./ #4): 90.794%	7. Discount % from Discount Matrix: 90%	8. Weighted Product (#4 X #7): 498.6
I. NamentSchonia OVACTERESOR	eisementraky roctoo) + 14 5	2 Zachtity Number: 93011
3. Urban or Rural: Urban	4. Total # of Students: 978	5. # of Students Eligible for NSLP: 899
6. %Students Eligible for NSLP (#5 / #4): 91.922%	7. Discount % from Discount Matrix: 90%	8. Weighted Product (#4 X #7): 880.2
1. Namesof School: LEBARRON PAR	SEIREM SCHOOL	22Entity Number: 93013
3. Urban or Rural: Urban	4. Total # of Students: 867	5.# of Students Eligible for NSLP: 790
6. %Students Eligible for NSEP (#5 / #4): 91-118%	7. Discount % from Discount Matrix: 90%	8. Weighted Product (#4 X #7): 780.3
I. Name of School: DEL VALLEY HOL	ESCHOOL: 4 1-4	2. Entity Number: 93014
3. Urban or Rural: Urban	4. Total # of Students: 1853	5. # of Students Eligible for NSLP: 1376
6. %Students Eligible for NSLP (#5 / #4): 74.257%	7. Discount % from Discount Matrix: 80%	8. Weighted Product (#4 X #7): 1482.4
I. Name of School: MARIAN MANOR	ELEMENTARY SCHOOL	2. Entity Number: 93016
3. U <b>rban or Rural:</b> Urban	4. Total # of Students: 668	5. # of Students Eligible for NSLP: 567
6. %Students Eligible for NSLP (#5 /- #4): 84.880%	7. Discount % from Discount Matrix: 90%	8. Weighted Product (#4 X #7): 601.2